



IA-32 Intel[®] Architecture Software Developer's Manual

Documentation Changes

February 2003

Notice: The IA-32 Intel[®] Architecture may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are documented in this specification update.

Document Number: 252046-003



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The IA-32 Intel® Architecture may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

I²C is a two-wire communications bus/protocol developed by Philips. SMBus is a subset of the I²C bus/protocol and was developed by Intel. Implementations of the I²C bus/protocol may require licenses from various entities, including Philips Electronics N.V. and North American Philips Corporation.

Intel, Pentium, Celeron, Intel SpeedStep, Intel Xeon and the Intel logo, and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2002–2003, Intel Corporation



Contents

Revision History	4
Preface.....	5
Summary Table of Changes.....	6
Documentation Changes	7

Revision History

Version	Description	Date
-001	Initial Release	November 2002
-002	Added 1-10 Documentation Changes. Removed old Documentation Changes items that already have been incorporated in the published Software Developer's manual	December 2002
-003	Added 9 -17 Documentation Changes Removed Documenation Change #6 - References to bits Gen and Len Deleted Removed Documenation Change #4 - VIF Information Added to CLI Discussion	February 2003

Preface

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This document is a compilation of documentation changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Affected Documents/Related Documents

Document Title	Document Number
<i>IA-32 Intel® Architecture Software Developer's Manual: Volume 1, Basic Architecture</i>	245470-009
<i>IA-32 Intel® Architecture Software Developer's Manual: Volume 2, Instruction Set Reference</i>	245471-009
<i>IA-32 Intel® Architecture Software Developer's Manual: Volume 3, System Programming Guide</i>	245472-009

Nomenclature

Documentation Changes include errors or omissions from the current published specifications. These changes will be incorporated in the next release of the Software Development Manual.

Summary Table of Changes

The following table indicates documentation changes which apply to the IA-32 Intel Architecture. This table uses the following notations:

Codes Used in Summary Table

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Summary Table of Documentation Changes

Number	DOCUMENTATION CHANGES
1	Description of FCOMI/FCOMIP Updated
2	Note Added to POP CS Instruction Entry in Table B-10
3	Information Added on resource_stall and WC_Buffer
4	Switching the L1 Data Cache between Adaptive and Shared Mode
5	FTW Storage Location Corrected
6	More Information on Invalid TSS Conditions Provided
7	Memory Storage Location of x87 FPU Data Registers Specified for FSAVE
8	Valid Interrupt Vector Discussion Has More Explanation
9	Information Added to Clarify Handling of Reserved Bits
10	Various Corrections in Volume 2: Table B-23
11	References to Bits GEn and Len Deleted
12	PSLLQ Pseudocode Error Corrected
13	STI and CLI Decision Tables Updated to Reflect VIF
14	Usage Note Added for Two Opcodes
15	#UD Exception Information Updated for Some Instructions
16	INT Pseudocode Updated with Flag Information
17	Errors Corrected in Opcode Table

Documentation Changes

All Documentation Changes will be incorporated into a future version of the IA-32 Intel® Architecture Software Developer's Manual.

1. Description of FCOMI/FCOMIP Updated

The IA-32 Intel® Architecture Software Developer's Manual, Volume 2: Instruction Set Reference, Chapter 3, Section: FCOMI/FCOMIP/ FUCOMI/FUCOMIP-Compare Floating Point Values and Set EFLAGS currently states:

The FUCOMI/FUCOMIP instructions always clear the OF flag in the EFLAGS register (regardless of whether an invalid-operation exception is detected); the FCOMI/FCOMIP instructions do not clear the OF flag.

It should state:

The FCOMI/FCOMIP and FUCOMI/FUCOMIP instructions clear the OF flag in the EFLAGS register (regardless of whether an invalid-operation exception is detected).

2. Note Added to POP CS Instruction Entry in Table B-10

The IA-32 Intel® Architecture Software Developer's Manual, Volume 2: Instruction Set Reference, Appendix B: Instructions Formats and Encodings, Table B-10: General Purpose Instruction Formats and Encodings has been updated by adding a note to the POP instruction. The note addresses a common error condition. The note is shown in the table segment below.

Table B-10. General Purpose Instruction Formats and Encodings [table segment only, entire table not shown...]	
POP – Pop a Segment Register from the Stack (Note: CS cannot be sreg2 in this usage.)	
segment register DS, ES	000 sreg2 111
segment register SS	000 sreg2 111
segment register FS, GS	0000 1111: 10 sreg3 001



3. Information Added on resource_stall and WC_Buffer

The IA-32 Intel® Architecture Software Developer's Manual, Volume 3: System Programming Guide, Appendix A, Table 1 will now include the following information on resource_stall and WC_Buffer. The new data is shown in the table segments included below:

Table A-1. Pentium 4 and Intel Xeon Processor Performance Monitoring Events for Non-Retirement Counting [table segment only, entire table not shown...]			
Event Name	Parameters	Parameter Value	Description
resource_stall			This event monitors the occurrence or latency of stalls in the Allocator.
	ESCR restrictions	MSR_ALF_ESCR0 MSR_ALF_ESCR1	
	Counter numbers per ESCR	ESCR0: 12, 13, 16 ESCR1: 14, 15, 17	
	ESCR Event Select	01H	ESCR[30:25]
	Event Masks	Bit 5: SBFULL	ESCR[24:9] A Stall due to lack of store buffers
	CCCR Select	01H	CCCR[15:13]
	Event Specific Notes		This event may not be supported in all models of the processor family.
WC_Buffer			This event counts Write Combining Buffer operations that are selected by the event mask.
	ESCR restrictions	MSR_DAC_ESCR0 MSR_DAC_ESCR1	
	Counter numbers per ESCR	ESCR0: 8, 9 ESCR1: 10, 11	
	ESCR Event Select	05H	ESCR[30:25]
	Event Masks	Bit 0: WCB_EVICTS 1: WCB_FULL_EVICT 2: WCB_HITM_EVICT	ESCR[24:9] WC Buffer evictions of all causes WC Buffer eviction: no WC buffer is available WC Buffer eviction: Store encountered a Hit Modified condition

4. Switching the L1 Data Cache between Adaptive and Shared Mode

The ability to switch the L1 Data Cache between adaptive and shared mode is now documented. In the *Intel Architecture Software Developer's Manual, Volume 2: Instruction Set Reference*, Chapter 3, Table 3-7; this capability impacts the description of ECX. See the EAX=1, ECX[10] in the following table segment:

Initial EAX Value	Information Provided About the Processor	
	Basic CPUID Information	
1H	EAX EBX	Version Information (Type, Family, Model, and Stepping ID) Bits 7-0: Brand Index Bits 15-8: CLFLUSH line size. (Value * 8 = cache line size in bytes) Bits 23-16: Number of logical processors per physical processor. Bits 31-24: Local APIC ID
	ECX	Bits 9-0: Reserved Bit 10: If this bit is 1, the L1 Data Cache may be placed in adaptive mode or shared mode. Mode selection is determined by Bit 24 of IA32_MISC_ENABLE (see Volume 3, Appendix B, Table B-1). If ECX[10] is 0, the ability to change the L1 Data Cache mode is not supported.
	EDX	Bits 63-11: Reserved Feature Information (see Figure 3-4 and Table 3-10)

Supporting information has also been added to the *IA-32 Intel® Architecture Software Developer's Manual, Volume 3: System Programming Guide*, Appendix B, Table B1. The description IA32_MISC_ENABLE[24] has been changed. This information has been provided in the table segment shown:

Register Address		Register Name Fields and Flags	Shared/ Unique	Bit Description
Hex	Dec			
1A0H	416	IA32_MISC_ENABLE	Shared	Enable Miscellaneous Processor Features. (R/W) Allows a variety of processor functions to be enabled and disabled.
		0		Fast-Strings Enable. When set, the fast-strings feature on the Pentium 4 processor is enabled(default); when clear, fast-strings are disabled.
		1		Reserved.
		2		x87 FPU Fopcode Compatibility Mode Enable. When set, fopcode compatibility mode is enabled; when clear (default), mode is disabled. See "Fopcode Compatibility Mode" in Chapter 8 of the <i>IA-32 Intel Architecture Software Developer's Manual, Volume 1</i> .
		3		Thermal Monitor Enable. When set, clock modulation controlled by the processor's internal thermal sensor is enabled; when clear (default), automatic clock modulation is disabled. (See Section 13.14.2., "Automatic Thermal Monitor".)



Table B-1. Special Fields within Instruction Encodings [table segment only...]				
Register Address		Register Name Fields and Flags	Shared/Unique	Bit Description
Hex	Dec			
		4		Split-Lock Disable. This debug feature is specific to the Pentium 4. When set, the bit causes an #AC exception to be issued instead of a split-lock cycle. Operating systems that set this bit must align system structures to avoid split-lock scenarios. When the bit is clear (the default), normal split-locks are issued to the bus.
		5		Reserved.
		6		Third-Level Cache Disable. (R/W) When set, the third-level cache is disabled; when clear (default) the third-level cache is enabled. This flag is reserved for processors that do not have a third-level cache. Note that this bit controls only the third-level cache, and then only if overall caching is enabled through the CD flag of control register CR0, the page-level cache controls, and/or the MTRRs (see Section 10.5.4., "Disabling and Enabling the L3 Cache").
		7		Performance Monitoring Available. (R) When set, performance monitoring is enabled; when clear, performance monitoring is disabled.
		8		Suppress Lock Enable. When set assert on of lock on the bus is suppressed during a Split Lock access. when clear (default) does not suppress lock.
		9		Prefetch Queue Disable. When set disables the prefetch queue. When clear (default) the prefetch queue is enabled.
		10		FERR# Interrupt Reporting Enable. (R/W) When set, interrupt reporting through the FERR# pin is enabled; when clear, this interrupt reporting function is disabled. When this flag is set and the processor is in the stop-clock state (STPCLK# is asserted), asserting the FERR# pin signals to the processor that an interrupt (such as, INIT#, BINIT#, INTR, NMI, SMI#, or RESET#) is pending and that the processor should return to normal operation to handle the interrupt. This flag does not affect the normal operation of the FERR# pin (to indicate an unmasked floating-point error) when the STPCLK# pin is not asserted.
		11		Branch Trace Storage Unavailable (BTS_UNAVILABLE). (R) When set, the processor does not support branch trace storage (BTS); when clear, BTS is supported.
		12		Precise Event Based Sampling Unavailable (PEBS_UNAVILABLE). (R) When set, the processor does not support precise event-based sampling (PEBS); when clear, PEBS is supported.

Table B-1. Special Fields within Instruction Encodings [table segment only..]				
Register Address		Register Name Fields and Flags	Shared/ Unique	Bit Description
Hex	Dec			
		23:13		Reserved.
		24		<p>L1 Data Cache Context Mode (R/W). When set to 1, this bit places the L1 Data Cache into shared mode. When set to 0 (the default), this bit places the L1 Data Cache into adaptive mode. In adaptive mode, the Page Directory Base Register contained in CR3 must be identical across all logical processors.</p> <p>Note: If the Context ID feature flag, ECX[10], is not set to 1 after executing CPUID with EAX = 1; the ability to switch modes is not supported and the BIOS must not alter the contents of IA32_MISC_ENABLE[24].</p>
		63:25		Reserved.



5. FTW Storage Location Corrected

The IA-32 Intel® Architecture Software Developer's Manual, Volume 2: Instruction Set Reference, Chapter 3, Section: FXSAVE - Save x87 FPU, MMX, SSE, and SSE2 State incorrectly indicates the memory storage location of the x87 FPU Tag Word (FTW). The storage location has been corrected to indicate a byte 4 offset (instead of a byte 5 offset).

A partial representation of the corrected table is shown below.

Table 3-14. Layout of FXSAVE and FXRSTOR Memory Region [table segment only, entire table is not shown...]

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0	
Rsrvd		CS		FPU IP				FOP			FTW	FSW		FCW		0
MXCSR_MASK		MXCSR				Rsrvd		DS	FPU DP							16
Reserved				ST0/MM0												32
Reserved				ST1/MM1												48
Reserved				ST2/MM2												64
Reserved				ST3/MM3												80
Reserved				ST4/MM4												96
Reserved				ST5/MM5												112
Reserved				ST6/MM6												128
Reserved				ST7/MM7												144
XMM0																160

6. More Information on Invalid TSS Conditions Provided

In the *A-32 Intel® Architecture Software Developer's Manual, Volume 3: System Programming Guide*, Chapter 5, Section: *Interrupt 10 - Invalid TSS Exception (#TS)*, Table 5-6 has been modified to include a more complete list of invalid conditions. The impacted part of the table is reproduced below with additions indicated by change bars.

Table 5-6. Invalid TSS Conditions [table segment only, entire table not shown...]	
Error Code Index	Invalid Condition
TSS segment selector index	TSS segment limit less than 67H for 32-bit TSS or less than 2CH for 16-bit TSS
	During an IRET task switch, the TI flag in the TSS segment selector indicates the LDT
	During an IRET task switch, the TSS segment selector exceeds descriptor table limit
	During an IRET task switch, the busy flag in the TSS descriptor indicates an inactive task
LDT segment selector index	Invalid LDT or LDT not present

In the *IA-32 Intel® Architecture Software Developer's Manual, Volume 3: System Programming Guide*, Chapter 5, Section: *Interrupt 13 – General Protection Exception (#GP)* includes a large bulleted list. The list has been corrected. The corrected portion of the list is shown below.

- Loading the CS register with a segment selector for a data segment or a null segment selector.
- Accessing memory using the DS, ES, FS, or GS register when it contains a null segment selector.
- Switching to a busy task during a call or jump to a TSS.
- Using a segment selector on a non-IRET task switch that points to a TSS descriptor in the current LDT. TSS descriptors can only reside in the GDT. This condition causes a #TS exception during an IRET task switch.
- Violating any of the privilege rules described in Chapter 4, *Protection*.
- Exceeding the instruction length limit of 15 bytes (this only can occur when redundant prefixes are placed before an instruction).

7. Memory Storage Location of x87 FPU Data Registers Specified for FSAVE

In the IA-32 Intel® Architecture Software Developer's Manual, Volume 1: Basic Architecture, Chapter 8, Figures 8-9 and 8-10 have been updated to include a short note about storage of the X87 data registers during the operation of FSAVE. Both updated figures are shown below:

Figure 8-9. Protected Mode x87 FPU State Image in Memory, 32-Bit Format





Figure 8-10. Real Mode x87 FPU State Image in Memory, 32-Bit Format



8. Valid Interrupt Vector Discussion Has More Explanation

In the *IA-32 Intel® Architecture Software Developer's Manual, Volume 3: System Programming Guide*, Chapter 8, Section 8.5.2 has been updated to include more information. See the data below. Change bars note the updated data.

Section 8.5.2 Valid Interrupt Vectors

The IA-32 architecture defines 256 vector numbers, ranging from 0 through 255 (see Section 5.2., *Exception and Interrupt Vectors*). The local and I/O APICs support 240 of these vectors (in the range of 16 to 255) as valid interrupts.

When an interrupt vector in the range of 0 to 15 is sent or received through the local APIC, the APIC indicates an illegal vector in its Error Status Register [see Section 8.5.3., *Error Handling*]. The IA-32 architecture reserves vectors 16 through 31 for predefined interrupts, exceptions, and Intel-reserved encodings (see Table 5-1); however, the local APIC does not treat vectors in this range as illegal.

When an illegal vector value (0 to 15) is written to an LVT entry and the delivery mode is Fixed (bits 8-11 equal 0), the APIC may signal an illegal vector error, without regard to whether the mask bit is set or whether an interrupt is actually seen on the input

9. Information Added to Clarify Handling of Reserved Bits

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3, Section: *MOV—Move to/from Control Registers, Description* subsection; the second paragraph changed to document an error condition that can occur when loading control registers. Note the change bar and bold text:

When loading control registers, programs should not attempt to change the reserved bits; that is, always set reserved bits to the value previously read. An attempt to change CR4's reserved bits will cause a general protection fault. Reserved bits in CR0 and CR3 remain clear after any load of those registers; attempts to set them have no impact. On Pentium 4, Intel Xeon and P6 family processors, CR0.ET remains set after any load of CR0; attempts to clear this bit have no impact.

10. Various Corrections in Volume 2: Table B-23

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3, Appendix B, Table B-23: *Floating-Point Structures and Encodings*; various corrections have been made. Cells impacted by corrections are listed:

[table segment only, entire table is not shown]	
Instruction and Format	Encoding
...	...
FDIV – Divide	
$ST(0) \leftarrow ST(0) \div 32\text{-bit memory}$	11011 000 : mod 110 r/m
$ST(0) \leftarrow ST(0) \div 64\text{-bit memory}$	11011 100 : mod 110 r/m
$ST(d) \leftarrow ST(0) \div ST(i)$	11011 d00 : 1111 R ST(i)
...	...
FDIVR – Reverse Divide	
$ST(0) \leftarrow 32\text{-bit memory} \div ST(0)$	11011 000 : mod 111 r/m
$ST(0) \leftarrow 64\text{-bit memory} \div ST(0)$	11011 100 : mod 111 r/m
$ST(d) \leftarrow ST(i) \div ST(0)$	11011 d00 : 1111 R ST(i)
...	...
FIMUL	
$ST(0) \leftarrow ST(0) \times 16\text{-bit memory}$	11011 110 : mod 001 r/m
$ST(0) \leftarrow ST(0) \times 32\text{-bit memory}$	11011 010 : mod 001 r/m
...	...
FISUB	
$ST(0) \leftarrow ST(0) - 16\text{-bit memory}$	11011 110 : mod 100 r/m
$ST(0) \leftarrow ST(0) - 32\text{-bit memory}$	11011 010 : mod 100 r/m
FISUBR	
$ST(0) \leftarrow 16\text{-bit memory} - ST(0)$	11011 110 : mod 101 r/m
$ST(0) \leftarrow 32\text{-bit memory} - ST(0)$	11011 010 : mod 101 r/m
...	...
FMULP – Multiply	
$ST(i) \leftarrow ST(0) \times ST(i)$	11011 110 : 1100 1 ST(i)

11. References to Bits Gen and Len Deleted

The *Intel Architecture Software Developer's Manual, Vol 3: System Programming Guide*, Chapter 15, Table 15-2 *Debug Exception Condition* referenced bits Gen and Len. They don't exist in this context; this error has been removed. The corrected table is shown:

Table 15-2. Debug Exception Conditions			
Debug or Breakpoint Condition	DR6 Flags Tested	DR7 Flags Tested	Exception Class
Single-step trap	BS = 1		Trap
Instruction breakpoint, at addresses defined by DRn and LENn	Bn = 1 and (Gn or Ln = 1)	R/Wn = 0	Fault
Data write breakpoint, at addresses defined by DRn and LENn	Bn = 1 and (Gn or Ln = 1)	R/Wn = 1	Trap
I/O read or write breakpoint, at addresses defined by DRn and LENn	Bn = 1 and (Gn or Ln = 1)	R/Wn = 2	Trap
Data read or write (but not instruction fetches), at addresses defined by DRn and LENn	Bn = 1 and (Gn or Ln = 1)	R/Wn = 3	Trap
General detect fault, resulting from an attempt to modify debug registers (usually in conjunction with in-circuit emulation)	BD = 1		Fault
Task switch	BT = 1		Trap

12. PSSLQ Pseudocode Error Corrected

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3, Section: *PSSLW/PSSLD/PSSLQ—Shift Packed Data Left Logical*; we corrected a typo in the PSSLQ pseudocode. The corrected entry is shown below.

```

PSSLQ instruction with 128-bit operand:
  IF (COUNT > 63)
  THEN
    DEST[128..0] ← 00000000000000000000000000000000H
  ELSE
    DEST[63-0] ← ZeroExtend(DEST[63-0] << COUNT);
    DEST[127-64] ← ZeroExtend(DEST[127-64] << COUNT);
  FI;

```

13. STI and CLI Decision Tables Updated to Reflect VIF

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3, Section: *CLI — Clear Interrupt Flag*; we have added VIF information to the relevant decision table. The new CLI decision table is shown below:

PE	VM	IOPL	CPL	PVI	VIP	VME	CLI Result
0	X	X	X	X	X	X	IF = 0
1	0	≥ CPL	X	X	X	X	IF = 0
1	0	< CPL	3	1	X	X	VIF = 0
1	0	< CPL	< 3	X	X	X	GP Fault
1	0	< CPL	X	0	X	X	GP Fault
1	1	3	X	X	X	X	IF = 0
1	1	< 3	X	X	X	1	VIF = 0
1	1	< 3	X	X	X	0	GP Fault
X = This setting has no impact.							

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3, Section: *STI — Set Interrupt Flag*; we have added VIF information to the relevant decision table. The new STI decision table is shown below:

PE	VM	IOPL	CPL	PVI	VIP	VME	STI Result
0	X	X	X	X	X	X	IF = 1
1	0	≥ CPL	X	X	X	X	IF = 1
1	0	< CPL	3	1	0	X	VIF = 1
1	0	< CPL	< 3	X	X	X	GP Fault
1	0	< CPL	X	0	X	X	GP Fault
1	0	< CPL	X	X	1	X	GP Fault
1	1	3	X	X	X	X	IF = 1
1	1	< 3	X	X	0	1	VIF = 1
1	1	< 3	X	X	1	X	GP Fault
1	1	< 3	X	X	X	0	GP Fault
X = This setting has no impact.							

14. Usage Note Added for Two Opcodes

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Appendix A, Table A-3; we have added a usage note to two opcodes. Only impacted table cells are shown. Note the bold text.

[table segment only, entire table not shown]								
	0	1	2	3	4	5	6	7
1	MOVUPS Vps, Wps MOVSS (F3) Vss, Wss MOVUPD (66) Vpd, Wpd MOVSD (F2) Vsd, Wsd	MOVUPS Wps, Vps MOVSS (F3) Wss, Vss MOVUPD (66) Wpd, Vpd MOVSD (F2) Vsd, Wsd	MOVLPS Wq, Vq MOVLPD (66) Vq, Ws MOVHPS Vq, Vq	MOVLPS Vq, Wq MOVLPD (66) Vq, Wq	UNPCKLPS Vps, Wq UNPCKLPD (66) Vpd, Wq	UNPCKHPS Vps, Wq UNPCKHPD (66) Vpd, Wq	MOVHPS Vq, Wq MOVHPD (66) Vq, Wq MOVHPS Vq, Vq	MOVHPS Wq, Vq MOVHPD (66) Wq, Vq
2	MOV Rd, Cd	MOV Rd, Dd	MOV Cd, Rd	MOV Dd, Rd	MOV Rd, Td^{††}		MOV Td, Rd^{††}	

NOTE:

[†] All blanks in the opcode map shown in Table A-3 are reserved and should not be used. Do not depend on the operation of these undefined opcodes.

^{††} Not currently supported after Pentium Pro and Pentium II families. Using this opcode on the current generation of processors will generate a #UD. For future processors, this value is reserved.

15. #UD Exception Information Updated for Some Instructions

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Chapter 3; we have updated #UD exception information in for the following instructions:

MOVD xmm, r32	MOVD r32, xmm	MOVDQA	MOVDQU
MOVQ xmm, m64	PACKSSWB/DW	PACKUSWB	PADDB/W/D
PADDSB/W	PADDUSB/W	PAND	PANDN PCMPEQB/W/
D	PCMPGTB/W/D	PMADDWD	PMULHWP/MULLW
POR	PSLLW/D/Q	PSRAW/D	PSRLW/D/QPSUBB/W/
D	PSUBSB/W	PSUBUSB/W	PUNPCKHBW/W/D/DQ
PUNPCKLBW/W/D/DQ	PXOR		

The updated #UD text is as follows.

Protected Mode Exceptions

#UD If EM in CR0 is set.

128-bit operations will generate #UD only if OSFXSR in CR4 is 0. Execution of 128-bit instructions on a non-SSE2 capable processor (one that is MMX capable) will result in the instruction operating on the mm registers, not #UD.

Real-Address Mode Exceptions

#UD If EM in CR0 is set.

128-bit operations will generate #UD only if OSFXSR in CR4 is 0. Execution of 128-bit instructions on a non-SSE2 capable processor (one that is MMX capable) will result in the instruction operating on the mm registers, not #UD.

16. INT Pseudocode Updated with Flag Information

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Section: *INT n/INTO/INT 3—Call to Interrupt Procedure*; we have updated the pseudocode to better reflect how some flags are cleared. The corrected listing is shown.

```

IF PE = 0
  THEN
    GOTO REAL-ADDRESS-MODE;
  ELSE (* PE = 1 *)
    IF (VM = 1 AND IOPL < 3 AND INT n)
      THEN
        #GP(0);
      ELSE (* protected mode or virtual-8086 mode interrupt *)
        GOTO PROTECTED-MODE;
    FI;
  FI;

REAL-ADDRESS-MODE:
  IF ((DEST * 4) + 3) is not within IDT limit THEN #GP; FI;
  IF stack not large enough for a 6-byte return information THEN #SS; FI;
  Push (EFLAGS[15:0]);
  IF ← 0; (* Clear interrupt flag *)
  TF ← 0; (* Clear trap flag *)
  AC ← 0; (*Clear AC flag*)
  Push(CS);
  Push(IP);
  (* No error codes are pushed *)
  CS ← IDT(Descriptor (vector_number * 4), selector));
  EIP ← IDT(Descriptor (vector_number * 4), offset)); (* 16 bit offset AND 0000FFFFH *)
END;

PROTECTED-MODE:
  IF ((DEST * 8) + 7) is not within IDT limits
    OR selected IDT descriptor is not an interrupt-, trap-, or task-gate type
    THEN #GP((DEST * 8) + 2 + EXT);
    (* EXT is bit 0 in error code *)
  FI;
  IF software interrupt (* generated by INT n, INT 3, or INTO *)
    THEN
      IF gate descriptor DPL < CPL
        THEN #GP((vector_number * 8) + 2 );
        (* PE = 1, DPL < CPL, software interrupt *)
      FI;
    FI;
  IF gate not present THEN #NP((vector_number * 8) + 2 + EXT); FI;
  IF task gate (* specified in the selected interrupt table descriptor *)
    THEN GOTO TASK-GATE;
    ELSE GOTO TRAP-OR-INTERRUPT-GATE; (* PE = 1, trap/interrupt gate *)
  FI;
END;

TASK-GATE: (* PE = 1, task gate *)
  Read segment selector in task gate (IDT descriptor);
  IF local/global bit is set to local
    OR index not within GDT limits

```

```

        THEN #GP(TSS selector);
    FI;
    Access TSS descriptor in GDT;
    IF TSS descriptor specifies that the TSS is busy (low-order 5 bits set to 00001)
        THEN #GP(TSS selector);
    FI;
    IF TSS not present
        THEN #NP(TSS selector);
    FI;
    SWITCH-TASKS (with nesting) to TSS;
    IF interrupt caused by fault with error code
        THEN
            IF stack limit does not allow push of error code
                THEN #SS(0);
            FI;
            Push(error code);
        FI;
    IF EIP not within code segment limit
        THEN #GP(0);
    FI;
END;
TRAP-OR-INTERRUPT-GATE
    Read segment selector for trap or interrupt gate (IDT descriptor);
    IF segment selector for code segment is null
        THEN #GP(0H + EXT); (* null selector with EXT flag set *)
    FI;
    IF segment selector is not within its descriptor table limits
        THEN #GP(selector + EXT);
    FI;
    Read trap or interrupt handler descriptor;
    IF descriptor does not indicate a code segment
        OR code segment descriptor DPL > CPL
        THEN #GP(selector + EXT);
    FI;
    IF trap or interrupt gate segment is not present,
        THEN #NP(selector + EXT);
    FI;
    IF code segment is non-conforming AND DPL < CPL
        THEN IF VM=0
            THEN
                GOTO INTER-PRIVILEGE-LEVEL-INTERRUPT;
                (* PE = 1, interrupt or trap gate, nonconforming *)
                (* code segment, DPL<CPL, VM = 0 *)
            ELSE (* VM = 1 *)
                IF code segment DPL ≠ 0 THEN #GP(new code segment selector); FI;
                GOTO INTERRUPT-FROM-VIRTUAL-8086-MODE;
                (* PE = 1, interrupt or trap gate, DPL<CPL, VM = 1 *)
            FI;
        ELSE (* PE = 1, interrupt or trap gate, DPL ≥ CPL *)
            IF VM = 1 THEN #GP(new code segment selector); FI;
            IF code segment is conforming OR code segment DPL = CPL
                THEN
                    GOTO INTRA-PRIVILEGE-LEVEL-INTERRUPT;
                ELSE
                    #GP(CodeSegmentSelector + EXT);
            FI;
        FI;
    FI;

```

```

(* PE = 1, interrupt or trap gate, nonconforming *)
(* code segment, DPL>CPL *)
    FI;
FI;
END;

INTER-PRIVILEGE-LEVEL-INTERRUPT
(* PE=1, interrupt or trap gate, non-conforming code segment, DPL<CPL *)
(* Check segment selector and descriptor for stack of new privilege level in current TSS *)
IF current TSS is 32-bit TSS
    THEN
        TSSstackAddress ← (new code segment DPL * 8) + 4
        IF (TSSstackAddress + 7) > TSS limit
            THEN #TS(current TSS selector); FI;
        NewSS ← TSSstackAddress + 4;
        NewESP ← stack address;
    ELSE (* TSS is 16-bit *)
        TSSstackAddress ← (new code segment DPL * 4) + 2
        IF (TSSstackAddress + 4) > TSS limit
            THEN #TS(current TSS selector); FI;
        NewESP ← TSSstackAddress;
        NewSS ← TSSstackAddress + 2;
FI;
IF segment selector is null THEN #TS(EXT); FI;
IF segment selector index is not within its descriptor table limits
    OR segment selector's RPL ≠ DPL of code segment,
    THEN #TS(SS selector + EXT);
FI;
Read segment descriptor for stack segment in GDT or LDT;
IF stack segment DPL ≠ DPL of code segment,
    OR stack segment does not indicate writable data segment,
    THEN #TS(SS selector + EXT);
FI;
IF stack segment not present THEN #SS(SS selector+EXT); FI;
IF 32-bit gate
    THEN
        IF new stack does not have room for 24 bytes (error code pushed)
            OR 20 bytes (no error code pushed)
            THEN #SS(segment selector + EXT);
        FI;
    ELSE (* 16-bit gate *)
        IF new stack does not have room for 12 bytes (error code pushed)
            OR 10 bytes (no error code pushed);
            THEN #SS(segment selector + EXT);
        FI;
FI;
IF instruction pointer is not within code segment limits THEN #GP(0); FI;
SS:ESP ← TSS(NewSS:NewESP) (* segment descriptor information also loaded *)
IF 32-bit gate
    THEN
        CS:EIP ← Gate(CS:EIP); (* segment descriptor information also loaded *)
    ELSE (* 16-bit gate *)
        CS:IP ← Gate(CS:IP); (* segment descriptor information also loaded *)
FI;
IF 32-bit gate

```

```

THEN
    Push(far pointer to old stack); (* old SS and ESP, 3 words padded to 4 *);
    Push(EFLAGS);
    Push(far pointer to return instruction); (* old CS and EIP, 3 words padded to 4*);
    Push(ErrorCode); (* if needed, 4 bytes *)
ELSE(* 16-bit gate *)
    Push(far pointer to old stack); (* old SS and SP, 2 words *);
    Push(EFLAGS(15..0));
    Push(far pointer to return instruction); (* old CS and IP, 2 words *);
    Push(ErrorCode); (* if needed, 2 bytes *)
FI;
CPL ← CodeSegmentDescriptor(DPL);
CS(RPL) ← CPL;
IF interrupt gate
    THEN IF ← 0 (*interrupt flag set to 0: disabled*);
FI;
TF ← 0;
VM ← 0;
RF ← 0;
NT ← 0;
END;

INTERRUPT-FROM-VIRTUAL-8086-MODE:
(* Check segment selector and descriptor for privilege level 0 stack in current TSS *)
IF current TSS is 32-bit TSS
    THEN
        TSSstackAddress ← (new code segment DPL * 8) + 4
        IF (TSSstackAddress + 7) > TSS limit
            THEN #TS(current TSS selector); FI;
        NewSS ← TSSstackAddress + 4;
        NewESP ← stack address;
    ELSE (* TSS is 16-bit *)
        TSSstackAddress ← (new code segment DPL * 4) + 2
        IF (TSSstackAddress + 4) > TSS limit
            THEN #TS(current TSS selector); FI;
        NewESP ← TSSstackAddress;
        NewSS ← TSSstackAddress + 2;
FI;
IF segment selector is null THEN #TS(EXT); FI;
IF segment selector index is not within its descriptor table limits
    OR segment selector's RPL ≠ DPL of code segment,
    THEN #TS(SS selector + EXT);
FI;
Access segment descriptor for stack segment in GDT or LDT;
IF stack segment DPL ≠ DPL of code segment,
    OR stack segment does not indicate writable data segment,
    THEN #TS(SS selector + EXT);
FI;
IF stack segment not present
    THEN #SS(SS selector+EXT);
FI;
IF 32-bit gate
    THEN
        IF new stack does not have room for 40 bytes (error code pushed)
            OR 36 bytes (no error code pushed);

```

```

        THEN #SS(segment selector + EXT);
    FI;
    ELSE (* 16-bit gate *)
        IF new stack does not have room for 20 bytes (error code pushed)
            OR 18 bytes (no error code pushed);
            THEN #SS(segment selector + EXT);
    FI;
FI;
IF instruction pointer is not within code segment limits
    THEN #GP(0);
FI;
tempEFLAGS ← EFLAGS;
VM ← 0;
TF ← 0;
RF ← 0;
IF service through interrupt gate
    THEN IF = 0;
FI;
TempSS ← SS;
TempESP ← ESP;
SS:ESP ← TSS(SS0:ESP0); (* Change to level 0 stack segment *)
(* Following pushes are 16 bits for 16-bit gate and 32 bits for 32-bit gates *)
(* Segment selector pushes in 32-bit mode are padded to two words *)
Push(GS);
Push(FS);
Push(DS);
Push(ES);
Push(TempSS);
Push(TempESP);
Push(TempEFlags);
Push(CS);
Push(EIP);
GS ← 0; (*segment registers nullified, invalid in protected mode *)
FS ← 0;
DS ← 0;
ES ← 0;
CS ← Gate(CS);
IF OperandSize = 32
    THEN
        EIP ← Gate(instruction pointer);
    ELSE (* OperandSize is 16 *)
        EIP ← Gate(instruction pointer) AND 0000FFFFH;
FI;
(* Starts execution of new routine in Protected Mode *)
END;

INTRA-PRIVILEGE-LEVEL-INTERRUPT:
(* PE=1, DPL = CPL or conforming segment *)
IF 32-bit gate
    THEN
        IF current stack does not have room for 16 bytes (error code pushed)
            OR 12 bytes (no error code pushed); THEN #SS(0);
        FI;
    ELSE (* 16-bit gate *)
        IF current stack does not have room for 8 bytes (error code pushed)

```



```

        OR 6 bytes (no error code pushed); THEN #SS(0);
    FI;
    IF instruction pointer not within code segment limit
        THEN #GP(0);
    FI;
    IF 32-bit gate
        THEN
        Push (EFLAGS);
        Push (far pointer to return instruction); (* 3 words padded to 4 *)
        CS:EIP ← Gate(CS:EIP); (* segment descriptor information also loaded *)
        Push (ErrorCode); (* if any *)
    ELSE (* 16-bit gate *)
        Push (FLAGS);
        Push (far pointer to return location); (* 2 words *)
        CS:IP ← Gate(CS:IP); (* segment descriptor information also loaded *)
        Push (ErrorCode); (* if any *)
    FI;
    CS(RPL) ← CPL;
    IF interrupt gate
        THEN IF ← 0; (*interrupt flag set to 0: disabled*)
    FI;
    TF ← 0;
    NT ← 0;
    VM ← 0;
    RF ← 0;
END

```

17. Errors Corrected In Opcode Table

In the *Intel Architecture Software Developer's Manual, Vol 2: Instruction Set Reference*, Appendix A, Table A-2; multiple errors have been corrected. Rows with corrected cells are shown (note the bold text).

[table segments only, entire table not shown]

	0	1	2	3	4	5	6	7
...
A	MOV				MOVS/ MOVSB Yb, Xb	MOVS/ MOVSW/ MOVSD Yv, Xv	CMPS/ CMPSB Yb, Xb	CMPS/ CMPSW/ CMPSD Xv, Yv
B	MOV immediate byte into byte register							
	AL	CL	DL	BL	AH	CH	DH	BH
C	Shift Grp 2 ^{1A}		RET lw	RET	LES Gv, Mp	LDS Gv, Mp	Grp 11 ^{1A} - MOV	
	Eb, lb	Ev, lb					Eb, lb	Ev, lb